Memo

To: Cedars Restaurant
From: Bob Corson
Date: July 12, 2001
Subject: Inspection of grease trap

On this date, at 11:15 am, I inspected the grease trap for the Cedars Restaurant, 515 N. West ByPass. This inspection was in response to a note from Omer Boyce that he had a call to clean the line that serves the restaurant. Mr. Boyce indicated that the line was almost stopped up but could not remember when the last time this line segment was cleaned.

According to Mr. Jim Dillard, Manager of the Cedars, the restaurant had called Drain Pro to unstop their private line and found it full of grease. When they flushed the restaurant's private line it sent the grease to the city sewer and they were afraid that it might cause a stoppage in the city sewer so they called the City.

The grease trap (30 lbs. ??) is located in the floor of the kitchen near the prep sink. I was unable to determine if there was a flow restrictor, however Mr. Dillard said that his employees complain about how slow the sinks drain that go through the grease trap. The prep sink, three vat sink and dishwasher are tributary to the grease trap. Mr. Dillard said that they clean the trap once a week. He also said that it had been a long time (years) since they had their sewer cleaned so he believed that the grease trap was working. He was aware if the requirements for grease traps as he installed a outside trap at their new location on South Campbell.

The restaurant is connected to the City sewer between manholes 9 and 10 on Map N 15 S E.

515 N West By Pass


MH A2
2+53W
0+00S
T-1252.40
FL-1248.07
FL-1246.07
7+11
7+16
END
7+09
601
3511
10
ST.
32
3526
3518
565
535
8"PVC
SE
SW
N15
519
526
N16
32
16
9
MH A3
2+50N
T-1253.50
FL-1249.58
513
17
509
WESTBY-PASS
8"PVC
8"PVC
9