City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 6/22/90

Report From:
- ☐ Citizen
- ☒ Fire Dept
- ☐ Sewer Maintenance
- ☐ Other

Received By: R. LYMAN
Referred To: —
Date of Incident: 6/21/90

Complainant Information:
Name PIER I IMPORTS
Address 1415 E. BATTLEFIELD
Phone 886-6848

Responsible Party Information:
Name *CHECK "FIRE INVESTIGATIONS"
Address FIRE STATION #1
Phone

Directions(if needed) STORM DRAIN IN PARKING LOT NW OF BUILDING, RESULTING FROM TRUCK ACCIDENT RUPTURING SADDLE TANK, LOSING < 50 GALS DIESEL FUEL.

Possible contamination of:
- ☐ soil
- ☐ groundwater
- ☒ surface water what body?
- ☐ other

Other Pertinent Information STORM SEWER

Who to contact:

☐ DNR 417-883-4033	☐ Bob Schaefer	☐ Sewer Const
☐ DNR 314-634-2436	☐ CU 831-8320	☐ Chemtrec 800-424-9300
☐ EPA 913-236-3378	☐ Street Dept	☐ DOT
☐ Fire Dept 864-1719	☐ Health Dept	☐ NRC 312-790-5500
☐ Police Dept 864-1719	☐ Sewer Maint	☐ Other

Details of Incident: A TRACTOR/TRUCK RUPTURED A SADDLE TANK SPILLING < 50 GALS DIESEL ON PIER I LOT. FIRE DEPT WAS CALLED AND PUT SAWDUST ON SPILL AND LEFT SCENE FOR TRUCKING COMPANY TO CLEAN UP.

Action needed: RESPONDED TO PAGE FROM FIRE DEPT. AT 6:50 P.M. REQUESTED BY "TOTAL COMPLIANCE CONSULTANTS", DENNIS GREESON, 861-5841.

1415 E. BATTLEFIELD

Investigation Results

ARRIVED ON SCENE SHORTLY AFTER 7:00 P.M.
MR GREESON SAID TRUCKING CO. WAS TO
CLEAN UP SPILL. WHEN THEY WERE CALLED
BY PIER I TO INVESTIGATE, TRUCKING CO.
HAD "MINIMALLY" CLEANED UP THE SAWDUST
AND WERE LEAVING BEFORE IT BEGAN RAINING.

MOST OF THE OIL WAS TRAPPED IN THE STORM
WATER DETENTION BASIN ON THE WEST SIDE
OF THE BUILDING (EAST SIDE OF FREMONT). TCC
PLACED A PALLET OVER WEIR ON DETENTION BASIN
ACTING AS A SKIMMER. VERY HEAVY
THUNDERSHOWERS FOLLOWED UNTIL 10:00
P.M.

DIESEL COULD BE SMELLED AND OBSERVED
IN STORM SEWER SOUTH OF FREMONT
AT LEAST TO PRIMROSE.

SPILL WAS NON-RECOVERABLE DUE TO
TORRENTIAL RAIN AND FLOODING OF
STORM SEWERS DOWNSTREAM.

Randy Lyman

6/22/90.