INTER OFFICE

MEMO

To: FILE - GREASE

From: Gene Pabst

Subject: Inspection at Applebee's (1855 E. Primrose) and Clarion Motel (3333 S. Glenstone).

Date: August 26, 1998

After a sanitary sewer backup on Sunday August 23, 1998 Randy Lyman and I did an inspection of the sanitary sewer in the area around Applebee's and Clarion Motel on August 25, 1998. We found very little evidence of grease in the sanitary sewer line. We went to Applebee's and pulled the cover of their outside interceptor. It appeared to be working properly with a small layer of grease on top of the water. We looked in their sampling manhole and found no evidence of grease.

I stopped at the Clarion Motel on August 26, 1998 and talked to Bill Reynolds, restaurant manager, and he informed me that they pump their interceptors once a month. We then talked to Curtis Miller, kitchen manager, and he said that they are pumped once a month. They have a contract with Blackburn/Gott to pump out their two in ground interceptors. Curtis said that he also uses a "anti-microbial" regularly.

1855 E. Primrose