INDUSTRIAL WASTE INVESTIGATION AND PERVEILLANCE STATUS REPORT

Mulder master

FIRM NAME E. W. Biggs

ADDRESS 405 WASHINGTON TELEPHONE 866-0470

PERSONNEL CONTACTED E. W. Biggs POSITION OWNER

POSITION

POSITION

ACTION INITIATED BY: CORSON, LYMAN, PABST, WRIGHT & CRISWELL

1) 3-5-73 - CONTACTED MR. BIGGS AND DIAGRAMMED FLOOR DRAINAGE AND SEWER SYSTEM. DYE WAS INEFFECTIVE BECAUSE OF CLOGGED DRAINS. BUILDING PLANS SHOWED INTERIOR DRAINS TO SANITARY SEWER EXTERIOR DRAINS CONTAINING BLOOD ETC. WERE DYE TRACED TO STORM SEWER. MAPS INCLUDED.

405 N. WASHINGTON


to storm ditch
sump
roof
mohair storage
loading Dock Railway Siding
roof
roof
#17
#19
#18
roof to lot
cooler
#20 cooler
restroom
Blood
#1
pipe from inside
#5
stairs down
office area
#5
#7
#9
water cooler
To storm ditch
#3
#6
#8
#21
roof to lot
#10
Vats Salt Solution
#13
#12
Vats
#11
#14
Blood
#2
#4 sink
roof
roof
roof
salt container
loading Dock railroad siding
salt container
sump
E.W. Biggs
3-5-73
Corson, Lyman, Criswell
Pabst, Wright

Basement Plan

Drain #

1 - grate - storm
2 - grate - storm
3 - grate - storm
4 - sink - storm
5 - drain - drying room
6 - drain - "
7 - drain - "
8 - drain - "
9 - drain - "
10 drain - vat room
11 " "
12 " "
13 " "
14 " "
15 drain - storage room
16 " "
17 grate - drying room
18 " "
19 " "
20 " "
21 " "



E. W. Biggs
3-5-73
Carson, Lyman, Criswell
Pabst, Wright.