City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 6/12/89

Report From:
- ☐ Citizen
- ☐ Fire Dept
- ☐ Sewer Maintenance
- ☐ Other

Received By: R. LYMAN
Referred To: R. CORSON
Date of Incident: 6/12/89

Complainant Information:
Name Queeta
Address BUILDING REGS.
Phone
Directions(if needed)

Responsible Party Information:
Name CHAPPEL TIRE *
Address 2140 S. CAMPBELL
Phone
* SOUTHSIDE TIRE & WHEEL.

Possible contamination of: ☐ soil ☐ groundwater
☒ surface water what body?
☐ other

Other Pertinent Information

Who to contact:

☒ DNR 417-883-4033	☐ Bob Schaefer	☐ Sewer Const
☐ DNR 314-634-2436	☐ CU 831-8320	☐ Chemtrec 800-424-9300
☐ EPA 913-236-3378	☐ Street Dept	☐ DOT
☐ Fire Dept 864-1719	☐ Health Dept	☐ NRC 312-790-5500
☐ Police Dept 864-1719	☐ Sewer Maint	☐ Other

Details of Incident: WASH TIRES IN 2 BAYS, WATER RUNS DOWN STREET. QUEETA DOES NOT THINK THEY HAVE ANY DRAINS IN BUILDING TO SANITARY SEWER.

Action needed: MAKE INSPECTION. TELL THEM YOU WILL REFER TO DNR BUT PERMIT WILL PROBABLY NOT BE GRANTED. SHOULD PUT DRAINS IN BUILDING TO DIVERT WASH WATER INTO.

2140 S. CAMPBELL

Investigation Results

Prior to a full investigation I obtained form A and form C from Ed Sears of Mo DNR.

Investigation revealed that tires + wheels were being washed in front of the repair bay. a wash rack inside the bay was not being used and a wash area outside was plugged up causing the wash water to run over this lot to Campbell St.

Mr. Bill Day indicated he would talk to the owner Mr Chappell on what measures they would take to stop the discharge.

I indicated I would get back with them within a week (June 20).