City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 11-27-89

Report From:
- ☐ Citizen
- ☒ Fire Dept
- ☐ Sewer Maintenance
- ☐ Other

Received By: Gene Pabst
Referred To:
Date of Incident: 11-27-89

Complainant Information:
Name
Address
Phone

Responsible Party Information:
Name Dr. Russell's Office
Address 1503 S. Glenstone
Phone 881-8593

Directions(if needed)

Possible contamination of:
- ☐ soil
- ☒ groundwater
- ☐ surface water what body?
- ☒ other Sanitary Sewer

Other Pertinent Information

Who to contact:

☐ DNR 417-883-4033	☐ Bob Schaefer	☐ Sewer Const
☐ DNR 314-634-2436	☐ CU 831-8320	☐ Chemtrec 800-424-9300
☐ EPA 913-236-3378	☐ Street Dept	☐ DOT
☐ Fire Dept 864-1719	☐ Health Dept	☐ NRC 312-790-5500
☐ Police Dept 864-1719	☐ Sewer Maint	☐ Other

Details of Incident: Fire Marshal Hosea Lawrence called at 12:55 P.M. (11-27-89) to report that he obtained explosive readings in a drain at Dr. Russell's office, 1503 S. Glenstone. Fire Marshall Lawrence thought we might want to check it out.

Action needed: Karen Chandler & I went to the area immediately. We arrived at 1:15 P.M. We immediately started checking the City Sanitary sewer manholes. The sewer line in question starts at Bennett St. behind Consumers & flows South to Portland & then flows West. We checked M.H. #26 Wye Map T-13 & obtained 0% LEL. We could not smell anything in the line. We then proceeded to M.H. #25 Wye Map T-13 We obtained 0% LEL and could smell nothing in the M.H. We then checked M.H. #24, Wye Map T-13. We obtained 0% LEL & could smell nothing. At this point we went to Dr. Russell's office. A Fire Dept. Pumper Truck was standing by. We talked to ~~Chief~~ Bill Baker, Bat. Chief ?, We went into Dr. Russell's

1503 S. Glenstone

Investigation Results

office. We went to the back of the Bldg. to the X-Ray Rm & Developing Rm. We could smell something but it didn't smell like gasoline. It smelled more like a rubber cement. We checked around with our explosion meter and obtained 0% LEL. We checked the drain in the developing Rm. and obtained 0% LEL. We could not tell if the drain in the developing Rm. was a real drain or a clean out. Fireman Baker suggested that Dr. Russell have a plumber look at his lines.

Fireman Baker did not know what the ~~Fireman~~ C.H. man found because he was gone when they ~~ap~~ arrived. Apparently his meter read a flammable gas but not natural.

We left it with Dr. Russell.

We called Fire Marshal Lawrence he was not there and left a message that we found nothing in the sanitary sewer.

We checked storm sewer behind Bldg. & found nothing

See Attach Maps.

Gene Palst



T-13
B
OF
37
33
9
11
GLENSTONE AVE.
Kentwood
1462
1503
1534
1506
M.H. No 5
10+50
M.H. No 4
7+50
M.H. No 3
4+32.5
M.H. No 1
1+40
15+00 M.H. #10
21+00 MH #12
Vacated



5-13
M.H. Nº 7 16+60
M.H. Nº 6 13+50
M.H. Nº 5, 10+50
M.H. #8, 9+00
M.H. #9, 12+00
M.H. #10, 15+00
M.H. #11, 18+00
District Boundary
Street widened 10' on West
GLENSTONE
COUNTR
VILL
OF
B - 37
L.H. & M.H. NUMBERS
LAST NUMBER